

MATERIAL SAFETY DATA SHEET

ISSUE DATE: 6/2/97

REVISED DATE: 05/30/09

Supersedes: Any Previous M.S.D.S. On This Product

DUCTMATE INDUSTRIES, INC.

EMERGENCY PHONE NUMBER: CHEM-TEL, INC. 1-800-255-3924

I. IDENTIFICATION

PRODUCT NAME: Quicksleeve Hi-Temperature Gasket DUCTMATE INDUSTRIES INC.
CHEMICAL FAMILY: Plastics 210 5th St.
FORMULA: (-CH₂)_X Charleroi, PA 15022

II. HAZARDOUS INGREDIENTS

<u>MATERIAL:</u>	<u>CAS</u>	<u>% WEIGHT</u>	<u>OSHA</u> <u>PEL (mg/m³)</u>	<u>ACGIH</u> <u>TLV (mg/m³)</u>
N/A				

III. PHYSICAL DATA

APPEARANCE: Fine Celled Foam
BOILING POINT: N/A
SPECIFIC GRAVITY: .03 g/cm³ (H₂O=1)
SOLUBILITY IN WATER: Negligible
ODOR: Characteristic
MELTING POINT: N/A

IV. HEALTH AND FIRST AID

CAUTION: Respiratory disorders may be aggravated by exposure to metallic dusts or fumes.
IN EYES: For contact with dust or particulates, flush eyes with large amounts of water. Eye injuries from solid particles should be treated by a physician immediately.
ON SKIN: Cuts or abrasions should be treated promptly with thorough cleansing of the affected area.
INGESTED: No need for first aid is anticipated if material is swallowed.
INHALATION: If large amounts of dusts, fumes, or particulates are generated, remove person to non-contaminated area.

V. FIRE AND EXPLOSION DATA

FLAMMABILITY CLASS:
FLASH POINT: N/A
EXTINGUISHING MEDIA: Water, Carbon Dioxide, Foam, Dry Chemical
UNUSUAL FIRE HAZARD: Material will float.
FIRE FIGHTING PROCEDURES: Wear self-contained positive pressure or pressure- demand breathing apparatus if exposed to fumes.

VI. SPILL OR LEAK PROCEDURES

Large/Small Spill: Avoid creating dusts when cleaning spill. Small pieces may be collected using a broom and shovel. Particulates and dusts may be collected by using a vacuum with a HEPA filter. Place collected material in a closed container.

VII. SPECIAL PROTECTION

VENTILATION: Whenever dusts, particulates, or fumes are generated, use appropriate local exhaust ventilation to keep exposures below the regulated limits.
EYE PROTECTION: Wear safety glasses with side shields.
HAND PROTECTION: Wear leather or other appropriate work gloves, if necessary for type of operation.
RESPIRATORY PROTECTION: Not normally needed. If permissible levels are exceeded, use NIOSH approved dust or fume respirator.

OTHER: Protective clothing- coveralls.

VIII. REACTIVITY DATA

STABILITY: Stable

INCOMPATIBILITY: N/A

CONDITIONS TO AVOID: Extreme heat above 316°C.

HAZARDOUS POLYMERIZATION: Will not occur.

HAZARDOUS DECOMPOSITION OR BY-PRODUCTS: Carbon Dioxide, Carbon Monoxide, Hydrocarbons

IX. SPECIAL PRECAUTIONS

As supplied this product does not present a health hazard. Processing of the product for some final uses can include formation of dusts, particulates, or fumes, some of which may present health hazards.

This information is taken from sources or based upon data believed to be reliable; however, DUCTMATE INDUSTRIES, INC. makes no warranty as to the absolute correctness or sufficiency of any of the foregoing or that additional or other measures may not be required under particular conditions.