

MATERIAL SAFETY DATA SHEET

ISSUE DATE: 1/8/96

REVISED DATE: 9/30/05

Supercedes: Any Previous M.S.D.S. On This Product

EMERGENCY PHONE NUMBER: CHEM-TEL INC. 1-800-255-3924

I. IDENTIFICATION

PRODUCT NAME: Neoprene Fabric

CHEMICAL FAMILY: Rubber Coated Fabric

FORMULA: Polychloroprene Rubber Coating over Fabric

DUCTMATE INDUSTRIES, INC.

1502 Industrial Drive

Monongahela, PA 15063

II. HAZARDOUS INGREDIENTS

MATERIAL:

Fibrous Glass

CAS

none

% WEIGHT

TLV

10mg/m³ for fiber diameters
< 7 microns

OSHA HAZARDOUS COMMUNICATIONS STANDARD, (29CFR1910.1200): Fibrous Glass

CALIFORNIA PROPOSITION 65: This product contains the following trace amounts of chemicals known to the state of California to be a cancer hazard:

III. PHYSICAL DATA

APPEARANCE: Black Polychloroprene Rubber Rubber Coating over Fabric

BOILING POINT: N/A

SOLUBILITY IN WATER: Negligible

VAPOR DENSITY: N/A

VOLATILE BY WEIGHT: N/A

EVAPORATION RATE: None

IV. HEALTH AND FIRST AID

CAUTION:

IN EYES: Not normally a route of exposure.

ON SKIN: Not normally a route of exposure.

INGESTED: Not normally a route of exposure.

INHALATION: Fumes from high temperature decomposition are toxic.

V. FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASS:

FLASH POINT: >250 degrees C TOC

EXTINGUISHING MEDIA: Water, Foam, Carbon Dioxide, Dry Chemical

UNUSUAL FIRE HAZARD: Electrostatic charge may build during unwind or rewind of coil

FIRE FIGHTING PROCEDURES: Wear self contained breathing apparatus with a full face piece in positive pressure demand mode. Water may be used to keep fire exposed rolls cool. Fumes from high temperature decomposition are toxic.

VI. SPECIAL PROTECTION

VENTILATION: Not normally necessary.

RESPIRATORY: Not normally necessary.

EYE PROTECTION: Not normally necessary.

HAND PROTECTION: Not normally necessary.

OTHER:

VII. REACTIVITY DATA

STABILITY: Stable

INCOMPATIBILITY: Strong Oxidizing Agents

HAZARDOUS DECOMPOSITION: By Fire or Thermal Decomposition: Chloride (Hcl), Carbon Monoxide (CO), Carbon Dioxide (CO₂), others undetermined.

HAZARDOUS POLYMERIZATION: Cannot Occur.

VIII. SPECIAL PRECAUTIONS

Wash with soap and water after handling.

This information is taken from sources or based upon data believed to be reliable; however, DUCTMATE INDUSTRIES, INC. makes no warranty as to the absolute correctness or sufficiency of any of the foregoing or that additional or other measures may not be required under particular conditions.